	Туре	Hits	Search Text	DBs
1	BRS	1487	438/\$ and (lcd lcds liquid adj crystal adj display)	USPAT
2	BRS	1238	438/\$ and (liquid adj crystal adj display)	USPAT
3	BRS	9	(438/\$ and (liquid adj crystal adj display)) and (HBr and "H.sub.2")	USPAT
4	BRS	33	(ITO IZO) and (HBr and "H.sub.2") same (plasma etch\$5 RIE)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
5	BRS	31	((ITO IZO) and (HBr and "H.sub.2") same (plasma etch\$5 RIE)) not ((438/\$ and (liquid adj crystal adj display)) and (HBr and "H.sub.2"))	EPO; JPO;
6	BRS	1	(ITO IZO) same (HBr and "H.sub.2") same (plasma etch\$5 RIE)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
7	BRS	30	(((ITO IZO) and (HBr and "H.sub.2") same (plasma etch\$5 RIE)) not ((438/\$ and (liquid adj crystal adj display)) and (HBr and "H.sub.2"))) not ((ITO IZO) same (HBr and "H.sub.2") same (plasma etch\$5 RIE))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
8	IS&R	1	("5007982").PN.	USPAT
9	IS&R	346	("438/714").CCLS.	USPAT
10	BRS	9	(("438/714").CCLS.) and (ITO IZO)	USPAT
11	BRS	2	(ITO IZO) same (HBr and "H.sub.2")	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
12	BRS	2	(indium adj oxide tin adj oxide) same (HBr and "H.sub.2")	USPAT
13	BRS	1	((indium adj oxide tin adj oxide) same (HBr and "H.sub.2")) not ((ITO IZO) same (HBr and "H.sub.2"))	USPAT

	Time Stamp	Comments	Error Definition	Errors
1	2001/04/13 16:18		Truncation Overflow. Return string from Server is: 5`0`0`438	1
2	2001/04/13 16:19		Truncation Overflow. Return string from Server is: 5`0`0`438	1
3	2001/04/16 09:03			0
4	2001/04/16 08:49	1		0
5	2001/04/16 10:56			0
6	2001/04/13 16:46			0
7	2001/04/13 17:02			0
8	2001/04/13 17:02			0
9	2001/04/13 17:27			0
10	2001/04/16 11:17			0
11	2001/04/16 08:50			0
12	2001/04/16 09:04			0
13	2001/04/16 09:05			0

	Туре	Hits	Search Text	DBs
14	BRS	0	treat\$3 near5 metal near5 plasma near5 ("H.sub.2")	USPAT
15	BRS	5	treat\$3 with metal with plasma with ("H.sub.2")	USPAT
16	BRS	8	treat\$3 with metal with (etch\$5 RIE) with ("H.sub.2")	USPAT
17	BRS	5	(treat\$3 with metal with (etch\$5 RIE) with ("H.sub.2")) not (treat\$3 with metal with plasma with ("H.sub.2"))	USPAT
18	BRS	0	treat\$3 with metal with (plasma etch\$5 RIE) with ("H.sub.2")	US-PGPUB; EPO; JPO; DERWENT; IBM TDB
19	BRS	1641	treat\$3 with metal with (plasma etch\$5 RIE)	US-PGPUB; EPO; JPO; DERWENT; IBM TDB
20	BRS	1	treat\$3 with metal with (plasma etch\$5 RIE) same (ITO IZO indium adj zinc adj oxide indium adj tin adj oxide)	US-PGPUB; EPO; JPO; DERWENT; IBM TDB
21	BRS	0	treat\$3 with metal with ("H.sub.2") same (ITO IZO indium adj zinc adj oxide indium adj tin adj oxide)	US-PGPUB; EPO; JPO; DERWENT; IBM TDB
22	BRS	0	treat\$3 with metal with ("H.sub.2") same (InSnO InZnO "In Sn O" "In Zn O")	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
23	BRS	0	treat\$3 with ("H.sub.2") same (InSnO InZnO "In Sn O" "In Zn O")	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
24	BRS	13		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
25	BRS	11	((ITO IZO) and (HBr and "H.sub.2" and "Cl.sub.2") same (etch\$5 RIE)) not ((438/\$ and (liquid adj crystal adj display)) and (HBr and "H.sub.2"))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
26	IS&R	1	("5286337").PN.	USPAT
27	BRS	65	Mohri and "H.sub.2"	USPAT
28	BRS	7	(Mohri and "H.sub.2") and HBr	USPAT

	Time Stamp	Comments	Error Definition	Errors
14	2001/04/16 09:09	-		О
15	2001/04/16 09:12			О
16	2001/04/16 09:15			0
17	2001/04/16 09:12			0
18	2001/04/16 09:16			О
19	2001/04/16 09:17			0
20	2001/04/16 09:32			0
21	2001/04/16 09:47			0
22	2001/04/16 09:50	N. I		0
23	2001/04/16 09:50			0
24	2001/04/16 11:00		Trùncation Overflow. Return string from Server is: 5`172985`	1
25	2001/04/16 11:01		Truncation Overflow. Return string from Server is: 5`172985`	1
	2001/04/16 11:19			0
	2001/04/16 11:20		1	0
	2001/04/16 11:20			0

	Туре	Hits	Search Text	DBs
29	BRS	65	Mohri and "H.sub.2"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
30	BRS	65	(Mohri and "H.sub.2") and (Mohri and "H.sub.2")	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
31	BRS	65	(Mohri and "H.sub.2") (Mohri and "H.sub.2")	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
32	BRS	7	(Mohri and "H.sub.2") and (ITO IZO)	USPAT
33	BRS	1	(HBr "H Br") with ("CH.sub.4" "C H.sub.4") same (ITO IZO)	USPAT
34	BRS	13	(HBr "H Br") with ("CH.sub.4" "C H.sub.4") and (ITO IZO)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
35	BRS	0	(HBr "H Br") with ("CH.sub.4" "C H.sub.4") same ((indium adj zinc adj oxide indium adj tin adj oxide))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
36	BRS	0	(HBr "H Br") with ("CH.sub.4" "C H.sub.4") same ((metal))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
37	BRS	80	(HBr "H Br") with ("CH.sub.4" "C H.sub.4") and ((metal))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
38	BRS	56	(HBr "H Br") with ("CH.sub.4" "C H.sub.4") same (etch\$5 rie plasma) and ((metal))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
39	BRS	47	(HBr "H Br") with ("CH.sub.4" "C H.sub.4") same (etch\$5 rie plasma) same (Al Cu W tungsten aluminum copper tin Sn indium In (metal))	
40	BRS	32	(HBr "H Br") with ("Cl.sub.2" and (HCl "H Cl")) same (etch\$5 rie plasma) same (Al Cu W tungsten aluminum copper tin Sn indium In (metal))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
41	BRS	1	((HBr "H Br") with ("CH.sub.4" "C H.sub.4") same (etch\$5 rie plasma) same (Al Cu W tungsten aluminum copper tin Sn indium In (metal))) and ((HBr "H Br") with ("Cl.sub.2" and (HCl "H Cl")) same (etch\$5 rie plasma) same (Al Cu W tungsten aluminum copper tin Sn indium In (metal)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
42	BRS	14256	(ITO IZO) and (etch\$5 plasma rie)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB

	Time Stamp	Comments	Error Definition	Errors
29	2001/04/16 11:21			0
30	2001/04/16 11:21			0
31	2001/04/16 11:21			0
32	2001/04/16 13:43			0
33	2001/04/16 13:45			0
34	2001/04/16 13:53			0
35	2001/04/16 13:57			0
36	2001/04/16 13:58			0
37	2001/04/16 13:59			0
38	2001/04/16 14:24			0
39	2001/04/16 14:39			0
40	2001/04/16 14:42			0
41	2001/04/16 14:42			0
42	2001/04/16 15:52			0

	Туре	Hits	Search Text	DBs
43	BRS	10096	(ITO IZO) and (etch\$5 rie)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
44	BRS	3124	(ITO IZO) same (etch\$5 rie)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB
45	BRS	845	(ITO IZO) same (etch\$5 rie)	EPO; JPO
46	BRS	498	(ITO IZO) with (etch\$5 rie)	EPO; JPO
47	BRS	218	ITO IZO)near3(etch\$5 rie	EPO; JPO
48	BRS	218	(ITO IZO) near3 (etch\$5 rie)	EPO; JPO
49	BRS	165	(ITO IZO) near2 (etch\$5 rie)	EPO; JPO
50	BRS	88	(ITO IZO) nearl (etch\$5 rie)	EPO; JPO
51	BRS	0	(ITO IZO) with (etch\$5 rie) and Mohri	EPO; JPO
52	BRS	0	(ITO IZO) with (etch\$5 rie) and Tsou	EPO; JPO
53	BRS	1	(ITO IZO) with (etch\$5 rie) and Hirano	EPO; JPO
54	BRS	1	"5723366"	EPO; JPO

	Time Stamp	Comments	Error Definition	Errors
43	2001/04/16 15:52			0
44	2001/04/16 15:55			0
45	2001/04/16 15:55			0
46	2001/04/16 15:55			0
47	2001/04/16 15:56			0
48	2001/04/16 15:56			0
49	2001/04/16 15:56			0
50	2001/04/16 15:57			0
	2001/04/16 15:57			0
	2001/04/16 15:57			0
	2001/04/16 16:00	Č.		0
54	2001/04/16 16:00	-		0